


MDC15K\_AUX\_V1  
NOR2508


焊接贴片螺母后，把  
150R/100W电阻拧在贴片螺母  
上，然后焊接电阻

SMTSO30110CTJ




H2

SMTSO3065CTS




H1

SMTSO3065CTS




150R/100W



SMTSO30110CTJ



Y2-01-104K-T-1



Y2-01-104K-T-1



STE-14D511KS


Y1-09-Y5U-1-D-331K




Y2-01-104K-T-1




STE-14D511KS



Y2-01-104K-T-1




STE-14D511KS




Y2-01-104K-T-1




NB90-12S-S-A



NB90-12S-S-A



2.54\_2P



HS1D

